
## Star Try Squares and Bevels.



## TRY SQUARES.

 No. 00, Concave Iron Hdle, Machinists'.

 Inch,
 4
 6
 8
 10
 12

 Per doz., \$17 00
 19 00
 22 00
 28 00
 35 00

No. 0, Iron Bound Rosewood Handle.

Inch, 4 6 8 10 12

Per doz., \$14 00 16 00 19 00 25 00 32 00

 No. 1, Polished Rosewood Handle.

 Inch,
 4
 6
 8
 10
 12

 Per doz.,
 \$7 00
 8 50
 10 00
 12 00
 16 00

No. 2, Pol'd Rosewood Hdle., Sq. Inside.

Inch, 4 6 8 10 12

Per doz., \$4 50 6 00 7 50 9 50 13 50


No. 3, Pol'd Rosewood Hdle., Sq. Inside.

Inch, 4 6 8 10 12

Per doz., \$3 50 4 50 5 25 6 00 7 25

Try and Mitre Squares. Same quality as Try Square No. 2.

Inch, 4 6 8 10 12 Per doz., \$6 00 7 50 9 00 11 50 16 00



## T BEVELS.

 No. 0, Iron Handle, Machinists'.

 Inch,
 6
 8
 10
 12

 Per doz.,
 \$10
 00
 11
 00
 12
 00
 13
 00

 No. 1, Polished Rosewood Handle.
 No. 3, Pol. Rosew'd Hdle., Not Gradua'd.

 Inch,
 6
 8
 10
 12
 Inch,
 6
 8
 10
 12

 Per doz.,
 \$8 00
 9 00
 10 00
 11 00
 Per doz.,
 \$4 50
 5 00
 5 50
 6 00

No. 2, Same as No. 1, Not Graduated.

Inch, 6 8 10 12
Per doz., \$6 50 7 50 8 50 9 50

No. 3, Pol. Rosew'd Hdle., Not Gradua'd.

Inch, 6 8 10 12
Per doz., \$4 50 5 00 5 50 6 00

Half dozen in a box.